

MEMO

Date: May 6, 2025
To: Resident Advisory Board
From: Sheri Bouvier, Contracts Administrator
Subject: Public Housing - Capital Fund Status Report and 5 Year Action Plan

As of May 6, 2025, the status of HACB Capital Fund construction activity follows:

HVAC Replacement – Winston Gardens: 20 HVAC to replace aged/failing equipment

- IFB issued 1/6/25.
- Contract awarded to Expert In Your Home for \$178,550.00
- Status: Work scheduled to begin May 20, 2025

Exterior Trim Painting – Oroville (43-15, 43-14)

- IFB issued 11/12/24.
- Contract awarded to: HB Restoration for \$78,250.00
- Status: Complete. Punch walk in one week.

Five-Year Environmental Review – All Sites

- RFP issued 8/27/24.
- Contract awarded to: E-Corp selected \$48,509.50
- Status: Final report complete. Next step - final publication and upload to HEROS.

HUD Safety & Security Grant – Winston Gardens (43-10)

- IFB issued: 8/15/2024
- Contract awarded to: Birchard Construction for \$496,711.00
- Status: Access control motors are in. Security cameras are being installed. Back gate posts in next week. Completion estimated at end of May.

Detailed Capital Fund 5 Year Action Plan:

Capital Fund 2025

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Bath Tub Refinishing** – Refinish bathtub at select public housing properties
- **Monument Signage**– Replace monument signs at Rhodes Terrace and Shelton Oaks
- **Roof Replacements** – Replace Roofs at select Gridley and Biggs properties
- **Trees/Landscaping** – Tree trimming and removal work amp wide

- **Paint Exteriors**– Paint the building exteriors Gridley and Biggs

Capital Fund 2026

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Water Heater Replacement Project**– Chico, replace water heaters which have reached the end of their useful life, in planning
- **Bathroom Tub/Shower Remodel** – Select concrete block units, in planning
- **Kitchen Remodel** – Select units, in planning
- **Exterior Lighting Upgrades** – Make exterior lighting upgrades amp wide
- **HVAC Replacement** – Replace HVAC at Winston Gardens

Capital Fund 2027

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Exterior Lighting Upgrades** – Upgrade exterior grounds and parking lot pole lighting to LED
- **Sewer Lateral Replacement** – Replacement damage or deteriorating sewer lateral line at select public housing units
- **Interior Upgrades** – Upgrade to energy efficient lighting fixtures
- **Water Heater Replacement Project**– Oroville, Gridley, Biggs, replace water heaters which have reached the end of their useful life, in planning
- **Paint Exteriors at Winston Gardens** – Paint the building exteriors Winston Gardens
- **HVAC Replacement** – Replace HVAC systems at select properties

Capital Fund 2028

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Trees/Landscaping** – Tree trimming and removal work amp wide
- **Sewer Lateral Replacement** – Replacement damage or deteriorating sewer lateral line at select public housing units
- **Site Work/ADA Improvement** – Site landscaping, ADA sidewalk improvements
- **Resurface Roads** – Resurface, seal coat, striping, curbs and gutters in parking area
- **HVAC Replacement** – Replace HVAC systems at select properties

Capital Fund 2029

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Paint Exterior** – Paint trim at select public housing properties
- **Roof Replacement** – Replace roofs at select Chico properties
- **Interior Upgrades** – Upgrade to energy efficient lighting fixtures
- **Bathroom Tub/Shower Replacement** – Replace tub and shower enclosures at Gridley and Biggs properties
- **Environmental Review** – Conduct required 5-year environmental review

Capital Fund Program - Five-Year Action Plan

Status: Draft

Approval Date:

Approved By:

Part I: Summary						
PHA Name : COUNTY OF BUTTE HSG AUTH		Locality (City/County & State)				
PHA Number: CA043		<input checked="" type="checkbox"/> Original 5-Year Plan		<input type="checkbox"/> Revised 5-Year Plan (Revision No:)		
A.	Development Number and Name	Work Statement for Year 1 2025	Work Statement for Year 2 2026	Work Statement for Year 3 2027	Work Statement for Year 4 2028	Work Statement for Year 5 2029
	BUTTE COUNTY (CA043000001)	\$1,156,572.00	\$1,156,572.00	\$1,156,572.00	\$1,156,572.00	\$1,156,572.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year		1	2025	
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,156,572.00
ID0000348	43-1A, 1B, 04, 2A,2B, 03 Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Flooring	ADA accessibility improvements to units		\$65,413.00
ID0000349	43-13 Kitchen Remodel(Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets)	Remodel Kitchen		\$60,000.00
ID0000350	43-14 Stucco, Siding/Painting,(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Roof, fascia, gutter, downspout, stucco, Siding and painting replacements.		\$50,000.00
ID0000351	43-1A,1B,04 Landscape Replacement(Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Electric Distribution)	Replace common area landscape and lighting		\$20,000.00
ID0000352	43-2A, 2B Landscape Replacement(Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains)	Replace common area landscape and lighting		\$80,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
1	2025			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000353	43-03 Landscape Replacement(Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Dwelling Unit-Site Work (1480)-Electric Distribution)	Replace common area landscape and lighting		\$40,000.00
ID0000354	43-13 Landscape Replacement(Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains)	Replace common area landscape and lighting		\$52,794.00
ID0000355	43-1A,1B,04, 2A,2B,03,10,13 Replace Porch/Sidewalk/ADA Improvements(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Site Work (1480)-Pedestrian paving)	Replace porch/Sidewalk and ADA improvements to unit entries		\$20,033.00
ID0000356	43-1A, 1B, 04, 2A, 2B, 03 Replace Water Heaters(Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Appliances)	Replace unit water heaters		\$50,000.00
ID0000357	43-1A, 1B, 2A, 2B, 03 Replace HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$60,000.00
ID0000358	43-1A, 1B, 2A, 2B, 04, 03 Roof, Fascia, Gutter, Downspout Rehab(Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc)	Replace Roof Fascia, Gutter and Downspouts, add Roof Anchors		\$20,000.00
ID0000359	Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administration		\$115,657.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
1	2025			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000360	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees. Lead Paint Hazard Assessment and Inventory		\$75,000.00
ID0000361	VCT Tile Replacement/ Asbestos Abatement Amp Wide(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$80,000.00
ID0000362	Operations(Operations (1406))	Operations		\$231,314.00
ID0000363	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0000364	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0000365	Management Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software Materials and Training needed for capital fund management		\$5,000.00
ID0000366	43-15 Install Retaining Wall(Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Storm Drainage)	Install retaining wall along the back of the east side units to stop hillside erosion.		\$75,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 2		2026		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,156,572.00
ID0000369	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0000370	43-10 Kitchen Remodel(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Kitchen		\$10,000.00
ID0000371	43-15 Stucco, Siding/Painting,(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Roof, fascia, gutter, downspout, stucco, Siding and painting replacements.		\$15,500.00
ID0000372	Operations(Operations (1406))	Operations		\$231,314.00
ID0000373	Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administration		\$115,657.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year		2026		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000374	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0000375	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees.		\$35,818.00
ID0000376	VCT Tile Replacement/ Asbestos Abatement AMP Wide(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$40,033.00
ID0000377	CA 43-1A,1B, 04, 2A,2B, 03, 10, 13, 14, 15 Site Work/ Landscaping/ADA (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Site landscaping, ADA, sidewalk replacements		\$27,794.00
ID0000378	Management Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software and Training needed for capital fund management		\$5,000.00
ID0000379	Energy Upgrades - Electric Amp Wide(Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing)	Replace unit light fixtures, panels, wiring and appliances for energy upgardes		\$50,000.00
ID0000380	Energy Upgrades - Building Amp Wide(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,	Replace building components for energy upgrade		\$20,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
2		2026		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)			
ID0000381	Electric and Low Voltage Upgrades, Amp Wide(Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Lighting,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Site Work (1480)-Lighting)	Replace and upgrade electrical and low voltage systems		\$20,000.00
ID0000382	43-01A, 01B, 02A, 02B, 04, 03, 10, 13, 14, 15 Resurface Roads(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Resurface roads, repave, seal coat, striping, curb gutter and sidewalk replacement.		\$5,000.00
ID0000383	43-1A, 1B, 04, 2A, 2B, 03, 10, 13, 14, 15 Replace Water Heaters(Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Appliances)	Replace unit water heaters		\$50,000.00
ID0000384	43-10, 13, 14, 15 Replace HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$50,000.00
ID0000385	43-1A, 1B, 2A, 2B, 03 Replace HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$50,000.00
ID0000386	43-01A, 1B, 2A, 2B, 03 Exterior Painting(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking)	Paint ext. of buildings. Abate lead paint as necessary		\$30,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 2 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000387	43-01A, 1B, 2A, 2B, 03, 10, 13, 14, 15 Interior Painting(Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Paint Interior of buildings. Abate lead paint as necessary		\$30,000.00
ID0000388	43-1A,1B,04, 2A,2B Sewer Lateral Replacement(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$50,000.00
ID0000389	43-13 Sewer Investigation and Replacement(Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$10,000.00
ID0000390	43-1A, 1B, 04, 2A,2B, 03 Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and	ADA accessibility improvements to units		\$18,500.00
ID0000391	43-1A,1b,04, 2A, 2B, 03 Install Replacement Windows(Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Windows)	Install replacement windows.		\$12,000.00
ID0000392	43-10, 13 Install Replacement Windows(Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Windows)	Install replacement windows.		\$10,000.00
ID0000393	43-01, 04, 02, 03, 10, 13, 14, 15 Laundry Room and Storage Room Imp(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Appliances,Non-	Laundry Room and Storage Building Improvements and Upgrades		\$20,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 2 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Flooring,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Laundry Areas,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area			
ID0000394	43-01A,1B, 2A, 2B, 03 Water Line Repipe(Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Re-pipe Water Lines		\$6,000.00
ID0000395	43-10 Water Line Repipe(Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks)	Re-pipe units		\$15,000.00
ID0000396	43-1A,1B,2A,2B,04,03, 10, 13, 14, 15 Door Replacement(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-	Replace Unit Interior, Exterior, Storage and Water Heater Vent Doors.		\$33,043.00
ID0000397	43-1A,1B,2A,2B,04,03 Screen Door Replacement(Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Install screen doors at units		\$12,000.00
ID0000398	Exterior Lighting Upgrades(Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Site Work (1480)-Lighting,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Site Work (1480)-Lighting)	Install Upgraded Exterior Lighting		\$10,000.00
ID0000399	Appliance Upgrade- Amp Wide(Dwelling Unit-Interior (1480)-Appliances)	Replace Unit Appliances (60)		\$36,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 2		2026		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000400	43-1A, 1B, 2A, 2B, 04, 03 Roof, Fascia, Gutter, Downspout Rehab, Roof Anchors(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits)	Replace Roof Fascia, Gutter, Downspouts, Roof Anchors for Fall Protection		\$20,000.00
ID0000401	43-10, 13, 14, 15 Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding)	Paint ext. of buildings. Abate lead paint as necessary.		\$10,000.00
ID0000402	43-14, 15 Bathroom Remodel(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and	Remodel Bathrooms		\$60,000.00
ID0000403	Lead Based Paint Abatement Amp Wide(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Siding)	lead based paint - removal, enclosure, encapsulation, and replacement		\$35,913.00
	Subtotal of Estimated Cost			\$1,156,572.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3 2027				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000410	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0000411	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees. 5 Year Environmental Review and Energy Audit consultant fees.		\$35,262.00
ID0000412	VCT Tile Replacement/ Asbestos Abatement AMP Wide(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$15,033.00
ID0000413	CA 43-1A,1B, 04, 2A,2B, 03, 10, 13, 14, 15 Site Work/ Landscaping/ADA (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Site landscaping, ADA, sidewalk replacements		\$15,000.00
ID0000414	Appliance Upgrade- Amp Wide(Dwelling Unit-Interior (1480)-Appliances)	Replace Unit Appliances (60)		\$36,000.00
ID0000415	43-01A, 01B, 04, 2A, 2B, 03 Bathroom Remodel(Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors)	Remodel Bathrooms		\$75,000.00
ID0000416	Landscaping Rehab - Tree Work, Amp Wide(Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other)	Prune, remove and replace landscaping trees that are diseased or impacting site infrastructure. Amp Wide		\$10,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3 2027				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000417	Energy Upgrades - Building Amp Wide(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Replace building components for energy upgrade		\$47,725.00
ID0000418	43-10, 13, 14 Replace HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$50,000.00
ID0000419	43-01, 04, 02, 03, 10, 13, 14, 15 Stucco, Siding/Painting.(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Roof, fascia, gutter, downspout, stucco, Siding and painting replacements.		\$60,000.00
ID0000420	43-03 Sewer Replacement(Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$43,787.00
ID0000421	43-10, 13, 14, 15 Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Appliances)	ADA accessibility improvements to units		\$12,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
3	2027			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000422	43-15 Kitchen Remodel(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Kitchen		\$60,000.00
ID0000423	43-13, 14 Install Replacement Windows(Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Windows)	Install replacement windows.		\$22,794.00
ID0000424	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0000425	43-1A,1B,04, 2A,2B Sewer Lateral Replacement(Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$50,000.00
ID0000426	43-10, 13, 14, 15 Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding)	Paint ext. of buildings. Abate lead paint as necessary.		\$10,000.00
ID0000427	Lead Based Paint Abatement Amp Wide(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Siding)	lead based paint - removal, enclosure, encapsulation, and replacement		\$75,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
4	2028			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,156,572.00
ID0000432	Appliance Upgrade Amp Wide(Dwelling Unit-Interior (1480)-Appliances)	Replace Unit Appliances (70)		\$10,000.00
ID0000433	43-14 Kitchen Remodel(Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks)	Remodel kitchen and replace unit cabinets and counter top systems		\$60,000.00
ID0000434	43-10, 13, 14, 15 Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding)	Paint ext. of buildings. Abate lead paint as necessary.		\$58,615.00
ID0000435	43-14, 15 Pre Fab Storage Sheds(Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Other)	Install Pre Fab Skid Type Storage Sheds at Units		\$10,000.00
ID0000436	43-14,15 Replace Porch/Sidewalk/ADA Improvements(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Exterior (1480)-Roofs)	Replace porch/Sidewalk and ADA improvements to unit entries		\$16,000.00
ID0000437	43-15 Install Retaining Wall(Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Storm Drainage)	Install retaining wall along the back of the east side units to stop hillside erosion.		\$10,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 4		2028		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000438	43-1A, 1B, 04, 2A, 2B, 03, 10, 13, 14, 15 Install Roof Mount P.V. Solar Panels(Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Landscape,Non-Dwelling Exterior (1480)-Canopies,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Roofs,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Site Utilities)	Install P.V. solar panels for common area electrical system.		\$20,000.00
ID0000439	43-13 Roof, Fascia, Gutter, Downspout Rehab, Roof Anchors(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits)	Replace Roof Fascia, Gutter, Downspouts and Roof Anchors		\$25,000.00
ID0000440	43-15 Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc)	ADA accessibility improvements to units		\$30,000.00
ID0000441	Landscaping Rehab - Tree Work, Amp Wide(Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other)	Prune, remove and replace landscaping trees that are diseased or impacting site infrastructure. Amp Wide		\$32,794.00
ID0000442	43-13 Sewer Investigation and Replacement(Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$10,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
4	2028			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000443	43-01A, 01B, 02A, 02B, 04, 03, 10, 13, 14, 15 Resurface Roads(Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Resurface roads, repave, seal coat, striping, curb gutter and sidewalk replacement.		\$40,000.00
ID0000444	43-10 Community Bldg. Interior and Exterior Remodel(Non-Dwelling Exterior (1480)-Balconies and Railings,Non-Dwelling Exterior (1480)-Canopies,Non-Dwelling Exterior (1480)-Doors,Non-Dwelling Exterior (1480)-Foundation,Non-Dwelling Exterior (1480)-Gutters - Downspouts,Non-Dwelling Exterior (1480)-Landings and Railings,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Mail Facilities,Non-Dwelling Exterior (1480)-Paint and Caulking,Non-Dwelling Exterior (1480)-Roofs,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Stairwells and Fire Escapes,Non-Dwelling Exterior (1480)-Tuck Pointing,Non-Dwelling Exterior (1480)-Windows,Non-Dwelling Interior (1480)-Appliances,Non-Dwelling Interior (1480)-Common Area Bathrooms,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Flooring,Non-Dwelling Interior (1480)-Common Area Kitchens,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Security)	Perform Interior and Exterior Remodel at Community Bldg.		\$10,000.00
ID0000445	Site Signage- Amp Wide(Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Signage)	Replace and Upgrade Existing Property Site Signage		\$25,000.00
ID0000446	VCT Tile Replacement/ Asbestos Abatement Amp Wide(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$50,000.00
ID0000447	CA 43-1A,1B, 04, 2A,2B, 03, 10, 13, 14, 15 Site Work/ Landscaping/ADA (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Site landscaping, ADA, sidewalk replacements		\$35,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 4 2028				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000448	Operations(Operations (1406))	Operations		\$231,314.00
ID0000449	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0000450	Management Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software and Training needed for capital fund management		\$5,000.00
ID0000451	Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administration		\$115,657.00
ID0000452	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0000453	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees.		\$50,000.00
ID0000454	Energy Upgrades - Electric Amp Wide(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Other)	Replace unit light fixtures, panels, wiring and appliances for energy upgardes		\$30,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 4		2028		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000455	43-01A, 01B, 04, 2A, 2B, 03 Bathroom Remodel(Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Bathrooms		\$60,000.00
ID0000456	Energy Upgrades - Building Amp Wide(Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding)	Replace building components for energy upgrade		\$50,000.00
ID0000457	Smoke Detectors and CO Detectors - Amp Wide(Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other)	Replace Smoke Detectors and CO Detectors Amp Wide		\$5,000.00
ID0000458	43-01,A, 1B, 04, 2A, 2B, 03, 10, 13, 14, 15 Replace Site and Unit Fencing (Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Landscape)	Replace site fencing and in front and back yards as needed.		\$21,659.00
ID0000459	43-15 Community Bldg. Interior and Exterior Remodel(Non-Dwelling Exterior (1480)-Foundation,Non-Dwelling Exterior (1480)-Gutters - Downspouts,Non-Dwelling Exterior (1480)-Landings and Railings,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Mail Facilities,Non-Dwelling Exterior (1480)-Other,Non-Dwelling Exterior (1480)-Paint and Caulking,Non-Dwelling Exterior (1480)-Roofs,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Stairwells and Fire Escapes,Non-Dwelling Exterior (1480)-Tuck Pointing,Non-Dwelling Exterior (1480)-Windows,Non-Dwelling Interior (1480)-Appliances,Non-Dwelling Interior (1480)-Common Area Bathrooms,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Flooring,Non-Dwelling Interior (1480)-Common Area Kitchens,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Exterior (1480)-Balconies and Railings,Non-Dwelling Exterior (1480)-Canopies,Non-	Perform Interior and Exterior Remodel at Community Bldg.		\$50,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year		2028		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Exterior (1480)-Doors,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Security,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area)			
ID0000460	Site Security -Amp Wide(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Playground Areas - Equipment,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Interior (1480)-Security,Non-Dwelling Site Work (1480)-Signage,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding)	Investigate and Install Site Security Measures		\$45,000.00
ID0000461	43-10 Landscape Replacement(Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains)	Replace common area landscape and lighting		\$8,533.00
ID0000462	43-10 Stucco, Siding/Painting.(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Roof, fascia, gutter, downspout, stucco, Siding and painting replacements.		\$30,000.00
	Subtotal of Estimated Cost			\$1,156,572.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5		2029		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,156,572.00
ID0000463	Operations(Operations (1406))	Operations		\$231,314.00
ID0000464	Administration(Administration (1410)-Salaries)	Administration		\$115,657.00
ID0000465	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0000466	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County fees.		\$100,000.00
ID0000467	VCT Tile Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic		\$30,000.00
ID0000468	Bathroom Remodel(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Bathroom		\$100,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5		2029		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000469	Roof Replacement(Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Roofs)	Replace Roof, Fascia, Vents, Gutter and Downspouts		\$250,000.00
ID0000470	Unit Interior ADA Accessibility Improvements (Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Kitchen Cabinets)	ADA Accessibility Improvements to Units		\$75,000.00
ID0000471	Water Heater Replacement(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing)	Replace Water Heaters		\$50,000.00
ID0000472	Site Work/Landscaping(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Site Landscaping, ADA Site Work, Sidewalk Replacement, Signage, Striping		\$50,000.00
ID0000473	Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other)	Paint exteriors of buildings. Abate lead based paint as necessary		\$80,000.00
ID0000474	Landscaping Rehab - Tree work(Dwelling Unit-Site Work (1480)-Landscape)	Prune, remove and replace landscaping trees that are diseased or impacting site infrastructure.		\$72,601.00
	Subtotal of Estimated Cost			\$1,156,572.00