

MEMO

Date: May 6, 2024
To: Resident Advisory Board
From: Sheri Bouvier, Contracts Administrator
Subject: Public Housing - Capital Fund Status Report and 5 Year Action Plan

As of May 6, 2024, the status of HACB Capital Fund construction activity follows:

- Public Housing (43-10) Access Control and Video Surveillance Systems, March 21, 2024 the HACB signed a contract with Gaynor Technologies to design, purchase, install, and maintain an access control and video surveillance systems at Winston Gardens. Gaynor Technologies will coordinate plans with HMR Architects and the General Contractor hired to construct the ACS infrastructure, perimeter fencing and upgrade exterior lighting to LED - Summer 2024.
- Public Housing – Roof Replacement Project (43-14, 43-15) The work includes reroofing of (70) Public Housing units and ancillary structures in Oroville (not including Winston Gardens). Contract was awarded to Above Board Construction and Roofing for \$580,653. ABC Roofing has completed installation of 44 residential roofs and 44 shed roofs at the Hammon Park and Oro Dam properties.
- Public Housing – All sites, ongoing. Abatement and replacement of asbestos-containing floor tiles; no units have been completed during the FY 2024; 153 of 232 Public Housing units have been completed overall. The work is being accomplished at unit turnover.

Detailed Capital Fund 5 Year Action Plan:

Capital Fund 2024

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Paint Trim** – Paint trim at 43-14 and 43-15 properties Hammon Park, Oro Dam. 7th and Pomona, Gardella Avenue, Casey Court
- **Roof Replacement** – Replace roofs at select Chico properties
- **Interior Upgrades** – Upgrade to energy efficient lighting fixtures
- **Bathroom Tub/Shower Replacement** – Replace tub and shower enclosures at Gridley and Biggs properties
- **Environmental Review** – conduct required 5-year environmental review

Capital Fund 2025

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Kitchen Cabinet Replacement** – Replace kitchen cabinets at Gridley and Biggs properties
- **Roof Replacements** – Replace Roofs at select Gridley and Biggs properties

- **Trees/Landscaping** – Tree trimming and removal work amp wide
- **Paint Exteriors**– Paint the building exteriors Gridley and Biggs

Capital Fund 2026

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Water Heater Replacement Project**– Chico, replace water heaters which have reached the end of their useful life, in planning
- **Bathroom Tub/Shower Remodel** – Select concrete block units, in planning
- **Kitchen Remodel** – Select units, in planning
- **Exterior Lighting Upgrades** – make exterior lighting upgrades amp wide
- **HVAC Replacement** – replace HVAC at Winston Gardens

Capital Fund 2027

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Exterior Lighting Upgrades** – Upgrade exterior grounds and parking lot pole lighting to LED
- **Sewer Lateral Replacement** – replacement damage or deteriorating sewer lateral line at select public housing units
- **Interior Upgrades** – upgrade to energy efficient lighting fixtures
- **Water Heater Replacement Project**– Oroville, Gridley, Biggs, replace water heaters which have reached the end of their useful life, in planning
- **Paint Exteriors at Winston Gardens** – Paint the building exteriors Winston Gardens
- **HVAC Replacement** – replace HVAC systems at select properties

Capital Fund 2028

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Trees/Landscaping** – Tree trimming and removal work amp wide
- **Sewer Lateral Replacement** – replacement damage or deteriorating sewer lateral line at select public housing units
- **Site Work/ADA Improvement** – site landscaping, ADA sidewalk improvements
- **Resurface Roads** – Resurface, seal coat, striping, curbs and gutters in parking area
- **HVAC Replacement** – replace HVAC systems at select properties

Housing Authority of the County of Butte

HUD Low Income Public Housing

Capital Fund Program - Summary by Capital Fund Project

Cash Available as of 5/06/2024

Capital Funds CF-21, CF-22, CF-23, CF-23E

Line No.	Summary by Development Account	CF-21			CF-22			CF-23			CF-23E Safety and Security Grant			Totals		
		Original	Obligated	Expended	Original	Obligated	Expended	Original	Obligated	Expended	Original	Obligated	Expended	Orig/Revised	Expended	Balance
1	100 Reserved Budget	4,153.00			3,800.00			3,601.00						11,554.00	-	11,554.00
2	1406 Operations (25% Max)	27,875.00	27,875.00	27,875.00	58,149.00	58,149.00	58,149.00	45,668.00	45,668.00					131,692.00	86,024.00	45,668.00
3	1408 Management Improvements							5,000.00						5,000.00	-	5,000.00
4	1410 Administration (10% Max)	91,336.00	91,336.00	91,336.00	111,325.00	111,325.00	111,325.00	91,336.00	91,336.00					293,997.00	202,661.00	91,336.00
14	1480 General Capital Fund Activity: Site Improvement, Dwelling Structures, Dwelling Equipment	794,154.00	794,154.00	793,740.76	943,782.00	909,208.28	466,917.06	1,001,774.00			225,639.00	98,062.59	-	2,965,349.00	1,260,657.82	1,704,691.18
		917,518.00	913,365.00	912,951.76	1,117,056.00	1,078,682.28	636,391.06	1,147,379.00	137,004.00	-	225,639.00	98,062.59	-	3,407,592.00	1,549,342.82	1,858,249.18
			99.55%	99.50%		96.56%	56.97%		12%	0%		43.46%	0.00%			

Capital Fund Program - Five-Year Action Plan

Status: Draft

Approval Date:

Approved By:

Part I: Summary						
PHA Name : COUNTY OF BUTTE HSG AUTH		Locality (City/County & State)				
PHA Number: CA043		<input checked="" type="checkbox"/> Original 5-Year Plan		<input type="checkbox"/> Revised 5-Year Plan (Revision No:)		
A.	Development Number and Name	Work Statement for Year 1 2024	Work Statement for Year 2 2025	Work Statement for Year 3 2026	Work Statement for Year 4 2027	Work Statement for Year 5 2028
	BUTTE COUNTY (CA043000001)	\$1,143,778.00	\$1,143,778.00	\$1,143,778.00	\$1,143,778.00	\$1,143,778.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
1	2024			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,143,778.00
ID0001	Operations(Operations (1406))	Operations		\$45,668.00
ID0002	Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administration		\$91,336.00
ID0003	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0004	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees. Lead Based Paint Survey		\$35,818.00
ID0005	VCT Tile Replacement/ Asbestos Abatement AMP Wide(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$50,000.00
ID0006	CA 43-1A,1B, 04, 2A,2B, 03, 10, 13, 14, 15 Site Work/ Landscaping/ADA (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Site landscaping, ADA, sidewalk replacements		\$15,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
1	2024			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0017	43-03 Sewer Replacement(Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$10,000.00
ID0088	43-14 Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks)	ADA accessibility improvements to units		\$10,000.00
ID0090	43-13, 14 Install Replacement Windows(Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Windows)	Install replacement windows.		\$10,000.00
ID0120	43-10 Install Replacement Windows(Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Windows)	Install replacement windows.		\$6,000.00
ID0139	43-13 Screen Doors(Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Install screen doors at units		\$5,000.00
ID0149	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$6,331.00
ID0161	43-01A,1B, 2A, 2B, 03 Water Line Repipe(Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing)	Re-pipe Water Lines		\$6,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year		1	2024	
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0164	43-1A,1B,04, 2A,2B Sewer Lateral Replacement(Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines -	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$10,000.00
ID0171	Management Improvements(Management Improvement (1408)-Staff Training,Management Improvement (1408)-Other,Management Improvement (1408)-System Improvements)	Software and Training needed for capital fund management		\$5,000.00
ID0183	43-10, 14, 15 Sewer Invesitgation and Replacement(Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$10,000.00
ID0185	43-15 Install Replacement Windows(Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Windows)	Install replacement windows.		\$16,000.00
ID0187	43-03, 10, 15 Replace HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$15,000.00
ID0189	43-10, 14, 15 Screen Doors(Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Install screen doors at units		\$9,000.00
ID0200	43-01A, 01B, 04, 2A, 2B, 03 Bathroom Remodel(Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical))	Remodel Bathrooms		\$30,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 1 2024				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0202	43-13 Bathroom Remodel(Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing)	Remodel Bathrooms		\$30,000.00
ID0203	43-14, 15 Bathroom Remodel(Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non	Remodel Bathrooms		\$30,000.00
ID0211	43-01A, 1B, 2A, 2B, 03, 10, 13, 14, 15 Interior Painting(Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Paint Interior of buildings. Abate lead paint as necessary		\$30,000.00
ID0213	43-13,14,15 Interior Painting(Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Interior Doors)	Paint Interior of buildings. Abate lead paint as necessary		\$30,000.00
ID0223	43-13,14,15 Sub Floor Replacement(Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks)	Replace Subfloor and flooring.		\$45,000.00
ID0225	5 Year Environmental Review Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Perform HUD required environmental review of Capital Fund activities		\$76,000.00
ID0232	43-10 Bathroom Remodel(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and	Remodel Bathrooms		\$30,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
	1	2024		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0234	CNA Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees. Audit consultant fees. CNA		\$16,313.00
ID0236	43-13, 14, 15 Water Line Repipe(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Re-pipe units		\$15,000.00
ID0243	Energy Upgrades - Building Amp Wide(Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing)	Replace building components for energy upgrade		\$30,000.00
ID0245	Smoke Detectors and CO Detectors - Amp Wide(Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine))	Replace Smoke Detectors and CO Detectors Amp Wide		\$2,000.00
ID0249	43-10 Door Replacement(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Replace Unit Interior, Exterior, Storage and Water Heater Vent Doors.		\$12,000.00
ID0253	43-10, 13, 14 Replace HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$11,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 1 2024				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0255	43-13 Stucco, Siding/Painting.(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Roof, fascia, gutter, downspout, stucco, Siding and painting replacements.		\$15,500.00
ID0258	43-10 Roof, Fascia, Gutter, Downspout Rehab(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits)	Replace Roof, Fascia, Gutter and Downspouts		\$16,000.00
ID0266	43-15 Landscape Replacement(Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains)	Replace front and back yard landscape		\$40,000.00
ID0290	43-1A,1B,2A,2B,04,03 Door Replacement(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Replace Unit Interior, Exterior, Storage and Water Heater Vent Doors.		\$37,812.00
ID0291	43-1A,1B,2A,2B,04,03 Screen Door Replacement(Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Install screen doors at units		\$12,000.00
ID0317	43-01, 04, 02, 03 Kitchen Remodel(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodos,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Kitchen		\$20,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
1	2024			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0324	Maintenace Shop Improvments(Non-Dwelling Construction-New Construction (1480)-Shop,Non-Dwelling Construction-New Construction (1480)-Storage Area,Non-Dwelling Exterior (1480)-Balconies and Railings,Non-Dwelling Exterior (1480)-Canopies,Non-Dwelling Exterior (1480)-Doors,Non-Dwelling Exterior (1480)-Foundation,Non-Dwelling Exterior (1480)-Gutters - Downspouts,Non-Dwelling Exterior (1480)-Landings and Railings,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Mail Facilities,Non-Dwelling Exterior (1480)-Other,Non-Dwelling Exterior (1480)-Paint and Caulking,Non-Dwelling Exterior (1480)-Roofs,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Stairwells and Fire Escapes,Non-Dwelling Exterior (1480)-Tuck Pointing,Non-Dwelling Exterior (1480)-Windows,Non-Dwelling Interior (1480)-Security,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area)	Construct and Remodel Maintenance Facilities to Improve Operations		\$80,000.00
ID0328	43-14, 43-15 Roof, Fascia, Gutter, Downspout Rehab(Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits)	Replace Roof Fascia, Gutter and Downspouts		\$150,000.00
ID0343	Water Intrusion Mitigation and Remediation Amp Wide(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios)	Water intrusion mitigation and remediation covers cleaning, drying, sanitizing and repairing. Mold remediation.		\$23,000.00
ID0345	Mailbox Replacement(Non-Dwelling Exterior (1480)-Mail Facilities)	upgrade old mailboxes		\$4,000.00
	Subtotal of Estimated Cost			\$1,143,778.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 2 2025				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,143,778.00
ID0016	43-1A, 1B, 04, 2A,2B, 03 Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Flooring	ADA accessibility improvements to units		\$65,413.00
ID0085	43-13 Kitchen Remodel(Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets)	Remodel Kitchen		\$60,000.00
ID0256	43-14 Stucco, Siding/Painting,(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc.,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Roof, fascia, gutter, downspout, stucco, Siding and painting replacements.		\$50,000.00
ID0270	43-1A, 1B, 04 Landscape Replacement(Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains)	Replace common area landscape and lighting		\$60,000.00
ID0271	43-2A, 2B Landscape Replacement(Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains)	Replace common area landscape and lighting		\$40,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
2	2025			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0272	43-03 Landscape Replacement(Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Dwelling Unit-Site Work (1480)-Electric Distribution)	Replace common area landscape and lighting		\$40,000.00
ID0273	43-13 Landscape Replacement(Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Dwelling Unit-Site Work (1480)-Electric Distribution)	Replace common area landscape and lighting		\$40,000.00
ID0274	43-1A, 1B, 04, 2A, 2B, 03, 10, 13 Replace Porch/Sidewalk/ADA Improvements(Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting)	Replace porch/Sidewalk and ADA improvements to unit entries		\$150,000.00
ID0275	43-1A, 1B, 04, 2A, 2B, 03 Replace Water Heaters(Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Appliances)	Replace unit water heaters		\$50,000.00
ID0278	43-1A, 1B, 2A, 2B, 03 Replace HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$60,000.00
ID0280	43-1A, 1B, 2A, 2B, 04, 03 Roof, Fascia, Gutter, Downspout Rehab(Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Gutters - Downspouts)	Replace Roof Fascia, Gutter and Downspouts		\$100,000.00
ID0282	Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administration		\$91,336.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 2		2025		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0283	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees. Lead Paint Hazard Assessment and Inventory		\$75,000.00
ID0284	VCT Tile Replacement/ Asbestos Abatement Amp Wide(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$80,000.00
ID0285	Operations(Operations (1406))	Operations		\$45,668.00
ID0286	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0287	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0288	Management Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software Materials and Training needed for capital fund management		\$5,000.00
ID0289	43-15 Install Retaining Wall(Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Storm Drainage)	Install retaining wall along the back of the east side units to stop hillside erosion.		\$75,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year		2	2025	
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0293	Appliance Upgrade - Amp Wide(Dwelling Unit-Interior (1480)-Appliances)	Replace Selected Unit Appliances		\$20,000.00
ID0341	43-1A, 1B, 2A, 2B, 03 Replace HVAC System(Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Electrical)	Replace HVAC systems		\$24,361.00
	Subtotal of Estimated Cost			\$1,143,778.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,143,778.00
ID0173	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0254	43-10 Kitchen Remodel(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Kitchen		\$60,000.00
ID0257	43-15 Stucco, Siding/Painting,(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Roof, fascia, gutter, downspout, stucco, Siding and painting replacements.		\$15,500.00
ID0294	Operations(Operations (1406))	Operations		\$45,668.00
ID0295	Administration(Administration (1410)-Salaries,Administration (1410)-Sundry,Administration (1410)-Other)	Administration		\$91,336.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3		2026		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0296	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0297	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees.		\$35,818.00
ID0298	VCT Tile Replacement/ Asbestos Abatement AMP Wide(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$70,000.00
ID0299	CA 43-1A,1B, 04, 2A,2B, 03, 10, 13, 14, 15 Site Work/ Landscaping/ADA (Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Site landscaping, ADA, sidewalk replacements		\$15,000.00
ID0300	Management Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software and Training needed for capital fund management		\$5,000.00
ID0301	Energy Upgrades - Electric Amp Wide(Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing)	Replace unit light fixtures, panels, wiring and appliances for energy upgardes		\$50,000.00
ID0302	Energy Upgrades - Building Amp Wide(Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior	Replace building components for energy upgrade		\$50,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)			
ID0303	Electric and Low Voltage Upgrades, Amp Wide(Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Lighting,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Site Work (1480)-Lighting)	Replace and upgrade electrical and low voltage systems		\$20,000.00
ID0304	43-01A, 01B, 02A, 02B, 04, 03, 10, 13, 14, 15 Resurface Roads(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Resurface roads, repave, seal coat, striping, curb gutter and sidewalk replacement.		\$40,000.00
ID0305	43-1A, 1B, 04, 2A, 2B, 03, 10, 13, 14, 15 Replace Water Heaters(Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Appliances)	Replace unit water heaters		\$50,000.00
ID0306	43-10, 13, 14, 15 Replace HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$50,000.00
ID0307	43-1A, 1B, 2A, 2B, 03 Replace HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$50,000.00
ID0308	43-01A, 1B, 2A, 2B, 03 Exterior Painting(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking)	Paint ext. of buildings. Abate lead paint as necessary		\$30,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0309	43-01A, 1B, 2A, 2B, 03, 10, 13, 14, 15 Interior Painting(Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Paint Interior of buildings. Abate lead paint as necessary		\$30,000.00
ID0312	43-1A,1B,04, 2A,2B Sewer Lateral Replacement(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$50,000.00
ID0313	43-13 Sewer Investigation and Replacement(Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$10,000.00
ID0314	43-1A, 1B, 04, 2A,2B, 03 Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and	ADA accessibility improvements to units		\$18,500.00
ID0316	43-1A,1b,04, 2A, 2B, 03 Install Replacement Windows(Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Windows)	Install replacement windows.		\$12,000.00
ID0320	43-10, 13 Install Replacement Windows(Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Windows)	Install replacement windows.		\$10,000.00
ID0321	43-01, 04, 02, 03, 10, 13, 14, 15 Laundry Room and Storage Room Imp(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Appliances,Non-	Laundry Room and Storage Building Improvements and Upgrades		\$20,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Flooring,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Laundry Areas,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area			
ID0322	43-01A,1B, 2A, 2B, 03 Water Line Repipe(Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Re-pipe Water Lines		\$6,000.00
ID0323	43-10 Water Line Repipe(Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks)	Re-pipe units		\$15,000.00
ID0325	43-1A,1B,2A,2B,04,03, 10, 13, 14, 15 Door Replacement(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-	Replace Unit Interior, Exterior, Storage and Water Heater Vent Doors.		\$33,043.00
ID0326	43-1A,1B,2A,2B,04,03 Screen Door Replacement(Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Install screen doors at units		\$12,000.00
ID0327	Exterior Lighting Upgrades(Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Site Work (1480)-Lighting,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Site Work (1480)-Lighting)	Install Upgraded Exterior Lighting		\$10,000.00
ID0331	Appliance Upgrade- Amp Wide(Dwelling Unit-Interior (1480)-Appliances)	Replace Unit Appliances (60)		\$36,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
3		2026		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0333	43-1A, 1B, 2A, 2B, 04, 03 Roof, Fascia, Gutter, Downspout Rehab(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits)	Replace Roof Fascia, Gutter and Downspouts		\$20,000.00
ID0334	43-10, 13, 14, 15 Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding)	Paint ext. of buildings. Abate lead paint as necessary.		\$75,000.00
ID0336	43-14, 15 Bathroom Remodel(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and	Remodel Bathrooms		\$60,000.00
ID0337	Lead Based Paint Abatement Amp Wide(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Siding)	lead based paint - removal, enclosure, encapsulation, and replacement		\$35,913.00
	Subtotal of Estimated Cost			\$1,143,778.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 4		2027		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,143,778.00
ID0054	43-01A, 1B, 2A, 2B, 03,04 Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other)	Paint ext. of buildings. Abate lead paint as necessary		\$80,000.00
ID0105	43-14, 15 Pre Fab Storage Sheds(Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Carports -Surface Garage)	Install Pre Fab Skid Type Storage Sheds at Units		\$20,000.00
ID0130	43-1A,1b,04, 2A, 2B, 03 Install Replacement Windows(Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Windows)	Install replacement windows.		\$12,000.00
ID0172	Operations(Operations (1406))	Operations		\$45,668.00
ID0174	Management Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software and Training needed for capital fund management		\$5,000.00
ID0175	Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administration		\$91,336.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
4	2027			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0176	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0177	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees. 5 Year Environmental Review and Energy Audit consultant fees.		\$35,262.00
ID0178	VCT Tile Replacement/ Asbestos Abatement AMP Wide(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$50,000.00
ID0179	CA 43-1A,1B, 04, 2A,2B, 03, 10, 13, 14, 15 Site Work/ Landscaping/ADA (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Site landscaping, ADA, sidewalk replacements		\$15,000.00
ID0181	Appliance Upgrade- Amp Wide(Dwelling Unit-Interior (1480)-Appliances)	Replace Unit Appliances (60)		\$36,000.00
ID0201	43-01A, 01B, 04, 2A, 2B, 03 Bathroom Remodel(Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors)	Remodel Bathrooms		\$75,000.00
ID0227	Landscaping Rehab - Tree Work, Amp Wide(Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Fencing)	Prune, remove and replace landscaping trees that are diseased or impacting site infrastructure. Amp Wide		\$60,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 4 2027				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0242	Energy Upgrades - Building Amp Wide(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc.,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Replace building components for energy upgrade		\$47,725.00
ID0292	43-10, 13, 14 Replace HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$50,000.00
ID0310	43-01, 04, 02, 03, 10, 13, 14, 15 Stucco, Siding/Painting.(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc.,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Roof, fascia, gutter, downspout, stucco, Siding and painting replacements.		\$60,000.00
ID0311	43-03 Sewer Replacement(Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Stripping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$43,787.00
ID0315	43-10, 13, 14, 15 Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Interior (1480)-Appliances)	ADA accessibility improvements to units		\$12,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 4		2027		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0318	43-15 Kitchen Remodel(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Kitchen		\$60,000.00
ID0319	43-13, 14 Install Replacement Windows(Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Exterior (1480)-Siding)	Install replacement windows.		\$10,000.00
ID0329	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0332	43-1A,1B,04, 2A,2B Sewer Lateral Replacement(Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$50,000.00
ID0335	43-10, 13, 14, 15 Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding)	Paint ext. of buildings. Abate lead paint as necessary.		\$75,000.00
ID0338	Lead Based Paint Abatement Amp Wide(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Siding)	lead based paint - removal, enclosure, encapsulation, and replacement		\$75,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
4	2027			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0339	43-10 Door Replacement(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Replace Unit Interior, Exterior, Storage and Water Heater Vent Doors.		\$20,000.00
ID0340	43-1A, 1B, 2A, 2B, 03 Replace HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$50,000.00
ID0342	Site Signage- Amp Wide(Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Signage)	Replace and Upgrade Existing Property Site Signage		\$30,000.00
ID0344	Water Intrusion Mitigation and Remediation Amp Wide(Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc)	Water intrusion mitigation and remediation covers cleaning, drying, sanitizing and repairing. Mold remediation.		\$23,000.00
	Subtotal of Estimated Cost			\$1,143,778.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5 2028				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,143,778.00
ID0012	Appliance Upgrade Amp Wide(Dwelling Unit-Interior (1480)-Appliances)	Replace Unit Appliances (70)		\$10,000.00
ID0058	43-14 Kitchen Remodel(Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks)	Remodel kitchen and replace unit cabinets and counter top systems		\$60,000.00
ID0084	43-10, 13, 14, 15 Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding)	Paint ext. of buildings. Abate lead paint as necessary.		\$58,615.00
ID0087	43-14, 15 Pre Fab Storage Sheds(Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Other)	Install Pre Fab Skid Type Storage Sheds at Units		\$10,000.00
ID0091	43-14,15 Replace Porch/Sidewalk/ADA Improvements(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Exterior (1480)-Roofs)	Replace porch/Sidewalk and ADA improvements to unit entries		\$16,000.00
ID0095	43-15 Install Retaining Wall(Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Storm Drainage)	Install retaining wall along the back of the east side units to stop hillside erosion.		\$75,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5		2028		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0135	43-1A, 1B, 04, 2A, 2B, 03, 10, 13, 14, 15 Install Roof Mount P.V. Solar Panels(Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Exterior (1480)-Roofs,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Site Utilities,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Lighting,Non-Dwelling Exterior (1480)-Canopies,Non-Dwelling Exterior (1480)-Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Landscape)	Install P.V. solar panels for common area electrical system.		\$75,000.00
ID0167	43-13 Roof, Fascia, Gutter, Downspout Rehab(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits)	Replace Roof Fascia, Gutter and Downspouts		\$25,000.00
ID0168	43-15 Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc)	ADA accessibility improvements to units		\$30,000.00
ID0180	Landscaping Rehab - Tree Work, Amp Wide(Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Landscape)	Prune, remove and replace landscaping trees that are diseased or impacting site infrastructure. Amp Wide		\$20,000.00
ID0182	43-13 Sewer Investigation and Replacement(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Interior (1480)-	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$10,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5		2028		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0192	43-01A, 01B, 02A, 02B, 04, 03, 10, 13, 14, 15 Resurface Roads(Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Resurface roads, repave, seal coat, striping, curb gutter and sidewalk replacement.		\$40,000.00
ID0206	43-10 Community Bldg. Interior and Exterior Remodel(Non-Dwelling Exterior (1480)-Paint and Caulking,Non-Dwelling Exterior (1480)-Roofs,Non-Dwelling Exterior (1480)-Windows,Non-Dwelling Interior (1480)-Appliances,Non-Dwelling Interior (1480)-Common Area Bathrooms,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Flooring,Non-Dwelling Interior (1480)-Common Area Kitchens,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Exterior (1480)-Foundation,Non-Dwelling Interior (1480)-Security,Non-Dwelling Exterior (1480)-Balconies and Railings,Non-Dwelling Exterior (1480)-Canopies,Non-Dwelling Exterior (1480)-Gutters - Downspouts,Non-Dwelling Exterior (1480)-Landings and Railings,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Doors,Non-Dwelling Exterior (1480)-Stairwells and Fire Escapes,Non-Dwelling Exterior (1480)-Mail Facilities,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Tuck Pointing)	Perform Interior and Exterior Remodel at Community Bldg.		\$64,813.00
ID0209	Site Signage- Amp Wide(Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Signage)	Replace and Upgrade Existing Property Site Signage		\$25,000.00
ID0215	VCT Tile Replacement/ Asbestos Abatement Amp Wide(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$50,000.00
ID0216	CA 43-1A,1B, 04, 2A,2B, 03, 10, 13, 14, 15 Site Work/ Landscaping/ADA (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Site landscaping, ADA, sidewalk replacements		\$35,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5 2028				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0217	Operations(Operations (1406))	Operations		\$45,668.00
ID0218	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0219	Management Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software and Training needed for capital fund management		\$5,000.00
ID0220	Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administration		\$91,336.00
ID0221	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0222	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees.		\$50,000.00
ID0230	Energy Upgrades - Electric Amp Wide(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Other)	Replace unit light fixtures, panels, wiring and appliances for energy upgardes		\$30,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5 2028				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0231	43-01A, 01B, 04, 2A, 2B, 03 Bathroom Remodel(Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Bathrooms		\$60,000.00
ID0241	Energy Upgrades - Building Amp Wide(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc.,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Replace building components for energy upgrade	\$50,000.00	
ID0244	Smoke Detectors and CO Detectors - Amp Wide(Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other)	Replace Smoke Detectors and CO Detectors Amp Wide		\$5,000.00
ID0247	43-01,A, 1B, 04, 2A, 2B, 03, 10, 13, 14, 15 Replace Site and Unit Fencing (Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Landscape)	Replace site fencing and in front and back yards as needed.		\$21,659.00
ID0248	43-15 Community Bldg. Interior and Exterior Remodel(Non-Dwelling Exterior (1480)-Balconies and Railings,Non-Dwelling Exterior (1480)-Canopies,Non-Dwelling Exterior (1480)-Doors,Non-Dwelling Exterior (1480)-Foundation,Non-Dwelling Exterior (1480)-Gutters - Downspouts,Non-Dwelling Exterior (1480)-Landings and Railings,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Mail Facilities,Non-Dwelling Exterior (1480)-Other,Non-Dwelling Exterior (1480)-Paint and Caulking,Non-Dwelling Exterior (1480)-Roofs,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Stairwells and Fire Escapes,Non-Dwelling Exterior (1480)-Tuck Pointing,Non-Dwelling Exterior (1480)-Windows,Non-Dwelling Interior (1480)-Appliances,Non-Dwelling Interior (1480)-Common Area Bathrooms,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Flooring,Non-Dwelling Interior (1480)-Common Area Kitchens,Non-Dwelling Interior (1480)-Common Area	Perform Interior and Exterior Remodel at Community Bldg.		\$50,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year		2028		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Painting,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Security,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area)			
ID0263	Site Security -Amp Wide(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Playground Areas - Equipment,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Interior (1480)-Security,Non-Dwelling Site Work (1480)-Signage)	Investigate and Install Site Security Measures		\$45,000.00
ID0267	43-10 Landscape Replacement(Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Dwelling Unit-Site Work (1480)-Electric Distribution)	Replace common area landscape and lighting		\$43,687.00
ID0281	43-10 Stucco, Siding/Painting,(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Roof, fascia, gutter, downspout, stucco, Siding and painting replacements.		\$30,000.00
	Subtotal of Estimated Cost			\$1,143,778.00