

MEMO

Date: April 8, 2026
To: Resident Advisory Board
From: Sheri Bouvier, Contracts Administrator
Subject: Public Housing - Capital Fund Status Report and 5 Year Action Plan

As of April 8, 2026, the status of HACB Capital Fund construction activity follows:

- Public Housing – Monument Sign Replacement, March 17, 2026 the HACB signed a contract with Visual Impact Signs to install new monument signs at the Rhodes Terrace and Shelton Oaks properties.
- Public Housing – All sites, ongoing. Abatement and replacement of asbestos-containing floor tiles; 167 of 232 Public Housing units have been completed overall. The work is being accomplished at unit turnover.

Detailed Capital Fund 5 Year Action Plan:

Capital Fund 2026

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Stucco Replacement/Paint Exteriors**– Paint the building exteriors Winston Gardens
- **Roof Replacement** – Replace roofs at select Chico properties
- **Interior Upgrades** – Upgrade to energy efficient lighting fixtures
- **Sewer Lateral Replacement** – replacement damage or deteriorating sewer lateral line at select public housing units
- **Trees/Landscaping** – Tree trimming and removal work Oroville, Gridley properties

Capital Fund 2027

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Kitchen Cabinet Replacement** – Replace kitchen cabinets at Gridley and Biggs properties
- **Roof Replacements** – Replace Roofs at select Gridley and Biggs properties
- **Bathroom Tub/Shower Replacement** – Replace tub and shower enclosures at Gridley and Biggs properties

Capital Fund 2028

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Kitchen Cabinet Replacement** – Select units, in planning
- **Exterior Lighting Upgrades** – make exterior lighting upgrades amp wide
- **HVAC Replacement** – replace HVAC at Winston Gardens
- **Paint Exteriors**– Paint the building exteriors Chico properties

-

Capital Fund 2029

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Exterior Lighting Upgrades** – Upgrade exterior grounds and parking lot pole lighting to LED
- **Sewer Lateral Replacement** – replacement damage or deteriorating sewer lateral line at select public housing units
- **Interior Upgrades** – upgrade to energy efficient lighting fixtures
- **Trees/Landscaping** – Tree trimming and removal work Oroville, Gridley properties
- **Water Heater Replacement Project**– Oroville, Gridley, Biggs, replace water heaters which have reached the end of their useful life, in planning
- **Environmental Review** – conduct required 5-year environmental review

Capital Fund 2030

- **ACM Tile Replacement** – All concrete-block units – ongoing
- **Bathroom Tub/Shower Remodel** – Select concrete block units, in planning
- **Trees/Landscaping** – Tree trimming and removal work amp wide
- **Site Work/ADA Improvement** – site landscaping, ADA sidewalk improvements
- **HVAC Replacement** – replace HVAC systems at select properties
- **Security Screen Doors** – install security doors and select properties

Capital Fund Program - Five-Year Action Plan

Status: Draft

Approval Date:

Approved By:

Part I: Summary						
PHA Name : COUNTY OF BUTTE HSG AUTH		Locality (City/County & State)				
PHA Number: CA043		<input checked="" type="checkbox"/> Original 5-Year Plan		<input type="checkbox"/> Revised 5-Year Plan (Revision No:)		
A.	Development Number and Name	Work Statement for Year 1 2026	Work Statement for Year 2 2027	Work Statement for Year 3 2028	Work Statement for Year 4 2029	Work Statement for Year 5 2030
	BUTTE COUNTY (CA043000001)	\$1,115,592.00	\$1,115,592.00	\$1,115,592.00	\$1,115,592.00	\$1,115,592.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 1		2026		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,115,592.00
ID0000478	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$5,000.00
ID0000479	Kitchen Remodel(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodos,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Replace cabinets, countertops, backsplash, appliances, faucets, sinks, paint, flooring, baseboards. Reframing walls, doors, windows.		\$10,000.00
ID0000480	Stucco and Siding (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Non-Dwelling Exterior (1480)-Balconies and Railings,Non-Dwelling Exterior (1480)-Landings and Railings,Non-Dwelling Exterior (1480)-Other,Non-Dwelling Exterior (1480)-Paint and Caulking,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Soffits,Non-Dwelling Site Work (1480)-Curb and Gutter,Non-Dwelling Site Work (1480)-Dumpster and Enclosures,Non-Dwelling Site Work (1480)-Fence Painting,Non-Dwelling Site Work (1480)-Playground Areas - Equipment,Non-Dwelling Site Work	Stucco and other Siding replacements including Painting		\$10,000.00
ID0000481	Operations(Operations (1406))	Operations		\$50,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 1		2026		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000482	Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administration		\$115,000.00
ID0000483	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0000484	VCT Tile Replacement/ Asbestos Abatement (Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Non-Dwelling Interior (1480)-Common Area Flooring)	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$35,000.00
ID0000485	Site Work/Landscaping/ADA (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Playground Areas - Equipment,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving,Non-Dwelling Site Work (1480)-Curb and Gutter,Non-Dwelling Site Work (1480)-Dumpster and Enclosures,Non-Dwelling Site Work (1480)-Fence Painting,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Playground Areas - Equipment,Non-Dwelling Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Site Utilities,Non-Dwelling Site Work (1480)-Storm	Site landscaping, ADA, sidewalk replacements		\$10,000.00
ID0000486	Management Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software and Training needed for capital fund management		\$5,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 1 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000487	Energy Upgrades - Electric Amp Wide(Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing)	Replace unit light fixtures, panels, wiring and appliances for energy upgardes		\$36,000.00
ID0000488	Energy Upgrades - Building Amp Wide(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Replace building components for energy upgrade	\$20,000.00	
ID0000489	Electric and Low Voltage Upgrades(Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Lighting,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Site Work (1480)-Lighting)	Replace and upgrade electrical and low voltage systems		\$20,000.00
ID0000490	Resurface Roads(Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping,Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving,Non-Dwelling Site Work (1480)-Curb and Gutter,Non-Dwelling Site Work (1480)-Dumpster and Enclosures,Non-Dwelling Site Work (1480)-Storm Drainage)	Resurface roads, repave, seal coat, striping, curb gutter and sidewalk replacement.		\$5,000.00
ID0000491	HVAC System (Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Common Area Dryers,Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems,Non-Dwelling Construction - Mechanical (1480)-Heating Equipment - System,Non-Dwelling Construction - Mechanical (1480)-Unit Sub-panels)	Replace HVAC systems		\$45,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 1 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000492	Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other)	Paint ext. of buildings. Abate lead paint as necessary		\$30,000.00
ID0000493	Interior Painting(Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Paint Interior of buildings. Abate lead paint as necessary		\$30,000.00
ID0000494	Sewer Investigation and Replacement(Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$10,000.00
ID0000495	Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and Showers)	ADA accessibility improvements to units		\$17,592.00
ID0000496	Window Replacement(Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Windows)	Install replacement windows.		\$10,000.00
ID0000497	Laundry Room and Storage Room Imp(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Appliances,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Flooring,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Laundry Areas,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area)	Laundry Room and Storage Building Improvements and Upgrades		\$20,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 1 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000498	Water Line Repipe(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Re-pipe Water Lines, under slab water leaks, rust or corroded pipes. Reroute pipes		\$6,000.00
ID0000500	Door Replacement(Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Exterior (1480)-Columns and Porches)	Replace Unit Interior, Exterior, Storage and Water Heater Vent Doors.		\$33,000.00
ID0000501	Screen Door Replacement(Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Install screen doors at units, security screen doors		\$12,000.00
ID0000502	Exterior Lighting Upgrades(Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Site Work (1480)-Lighting,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Site Work (1480)-Lighting)	Install Upgraded Exterior Lighting		\$10,000.00
ID0000503	Appliance Upgrade(Dwelling Unit-Interior (1480)-Appliances)	Replace Unit Appliances		\$36,000.00
ID0000505	Bathroom Remodel(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Bathrooms		\$60,000.00
ID0000506	Lead Based Paint Survey and Abatement(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Siding)	lead based paint - identification, testing, removal, enclosure, encapsulation, and replacement, and clearance		\$36,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
1	2026			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000510	Landscape Replacement(Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains)	Replace common area landscape and lighting		\$80,000.00
ID0000513	Replace Porch/Sidewalk/ADA Improvements(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Site Work (1480)-Pedestrian paving)	Replace porch/Sidewalk and ADA improvements to unit entries		\$20,000.00
ID0000514	Replace Water Heaters(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing)	Replace unit water heaters		\$50,000.00
ID0000515	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees. Lead Paint Hazard Assessment and Inventory, Asbestos Testing and Clearance and Inventory		\$75,000.00
ID0000519	Install Retaining Wall(Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Storm Drainage)	Install retaining wall along the back of the east side units to stop hillside erosion.		\$5,000.00
ID0000522	Roof, Fascia, Gutter, Downspout Rehab, Roof Anchors(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits)	Replace Roof Fascia, Gutter, Downspouts, Roof Anchors for Fall Protection		\$20,000.00
ID0000524	Asbestos, Lead and Hazardous Materials (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior	Testing, Abatement and Clearance Testing of Hazardous Materials		\$75,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year		2026		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	(1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes,Dwelling Unit-Exterior (1480)-Tuck-Pointing,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Non-Dwelling Exterior (1480)-Balconies and Railings,Non-Dwelling Exterior (1480)-Canopies,Non-Dwelling Exterior (1480)-Doors,Non-Dwelling Exterior (1480)-Foundation,Non-Dwelling Exterior (1480)-Gutters - Downspouts,Non-Dwelling Exterior (1480)-Landings and Railings,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Mail Facilities,Non-Dwelling Exterior (1480)-Paint and Caulking,Non-Dwelling Exterior (1480)-Roofs,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Stairwells and Fire Escapes,Non-Dwelling Exterior (1480)-Tuck Pointing,Non-Dwelling Exterior (1480)-Windows,Non-Dwelling Interior (1480)-Administrative Building,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Flooring,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving,Non-Dwelling Site Work (1480)-Curb and Gutter,Non-Dwelling Site Work (1480)-Dumpster and Enclosures,Non-Dwelling Site Work (1480)-Fence Painting,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Site Utilities,Non-Dwelling Site Work (1480)-Storm Drainage,Dwelling Unit - Demolition (1480))			
ID0000525	Security Cameras and Surveillance Systems (Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Windows,Non-Dwelling Exterior (1480)-Other)	Security Cameras and Safety Surveillance Systems		\$20,000.00
ID0000554	Pre Fab Storage Sheds(Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Other)	Install Pre Fab Skid Type Storage Sheds at Units		\$10,000.00
ID0000563	Community Bldg. Interior and Exterior Remodel(Non-Dwelling Exterior (1480)-Canopies,Non-Dwelling Exterior (1480)-Doors,Non-Dwelling Exterior (1480)-Foundation,Non-Dwelling Exterior (1480)-Gutters - Downspouts,Non-Dwelling Exterior (1480)-Landings and Railings,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Mail Facilities,Non-Dwelling Exterior (1480)-Paint and Caulking,Non-Dwelling Exterior (1480)-Roofs,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Stairwells and Fire Escapes,Non-Dwelling Exterior (1480)-Tuck Pointing,Non-Dwelling Exterior (1480)-Balconies and	Perform Interior and Exterior Remodel at Community Bldg.		\$10,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year		2026		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Dwelling Exterior (1480)-Windows,Non-Dwelling Interior (1480)-Appliances,Non-Dwelling Interior (1480)-Common Area Bathrooms,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Flooring,Non-Dwelling Interior (1480)-Common Area Kitchens,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Security)			
ID0000598	Landscaping Rehab - Tree Work, Amp Wide(Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other)	Prune, remove and replace landscaping trees that are diseased or impacting site infrastructure.		\$10,000.00
ID0000605	Fencing (Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving,Non-Dwelling Site Work (1480)-Curb and Gutter,Non-Dwelling Site Work (1480)-Dumpster and Enclosures,Non-Dwelling Site Work (1480)-Fence Painting,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)-Playground Areas - Equipment,Non-Dwelling Site Work (1480)-Site Utilities)	Replace site fencing and in front and back yards as needed.		\$15,000.00
ID0000609	Water Intrusion Mitigation and Remediation (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Non-Dwelling Exterior (1480)-Balconies and Railings,Non-Dwelling Exterior (1480)-Canopies,Non-Dwelling Exterior (1480)-Doors,Non-Dwelling Exterior (1480)-Foundation,Non-Dwelling Exterior (1480)-Gutters - Downspouts,Non-Dwelling Exterior	Water intrusion mitigation and remediation covers cleaning, drying, sanitizing and repairing. Mold remediation.		\$10,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 1 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	(1480)-Lighting,Non-Dwelling Exterior (1480)-Mail Facilities,Non-Dwelling Exterior (1480)-Other,Non-Dwelling Exterior (1480)-Paint and Caulking,Non-Dwelling Exterior (1480)-Roofs,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Stairwells and Fire Escapes,Non-Dwelling Exterior (1480)-Tuck Pointing,Non-Dwelling Exterior (1480)-Windows,Non-Dwelling Interior (1480)-Administrative Building,Non-Dwelling Interior (1480)-Appliances,Non-Dwelling Interior (1480)-Common Area Bathrooms,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Flooring,Non-Dwelling Interior (1480)-Common Area Kitchens,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Day Care Center,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Family Investment Center,Non-Dwelling Interior (1480)-Laundry Areas,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Security,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area)			
ID0000610	Smoke Detectors and CO Detectors (Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Other,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Other)	Replace Smoke Detectors and CO Detectors		\$5,000.00
ID0000611	Install Solar Panels(Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Exterior (1480)-Carports -Surface Garage)	Install solar panels for common area electrical system.		\$10,000.00
ID0000612	Replace and Upgrade Existing Property Site Signage(Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Signage)	Replace and Upgrade Existing Property Site Signage		\$10,000.00
ID0000620	Site Security (Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Stripping,Non-Dwelling Exterior (1480)-Doors,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Other,Non-Dwelling Exterior (1480)-Windows,Non-Dwelling Interior (1480)-Administrative Building,Non-Dwelling Interior (1480)-Appliances,Non-Dwelling Interior (1480)-Common Area Bathrooms,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area	Perimeter fencing, access control gates, LED Lighting upgrade, deadbolt locks, electronic locks, security window screens, security door screens		\$5,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 1 2026				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Flooring,Non-Dwelling Interior (1480)-Common Area Kitchens,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Day Care Center,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Family Investment Center,Non-Dwelling Interior (1480)-Laundry Areas,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Security,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Signage)			
ID0000621	Gas Distribution Systems Upgrade(Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Other,Non-Dwelling Construction - Mechanical (1480)-Central Boiler,Non-Dwelling Construction - Mechanical (1480)-Central Chiller,Non-Dwelling Construction - Mechanical (1480)-Common Area Dryers,Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems,Non-Dwelling Construction - Mechanical (1480)-Electric Distribution,Non-Dwelling Construction - Mechanical (1480)-Fire Suppression System,Non-Dwelling Construction - Mechanical (1480)-Generator,Non-Dwelling Construction - Mechanical (1480)-Heating Equipment - System,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters,Non-Dwelling Construction - Mechanical (1480)-Security - Fire Alarm,Non-Dwelling Construction - Mechanical (1480)-Smoke/Fire Detection,Non-Dwelling Construction - Mechanical (1480)-Unit Sub-panels,Non-Dwelling Exterior (1480)-Other,Non-Dwelling Interior (1480)-Appliances,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Site Work (1480)-Site Utilities)	upgrade gas distribution system, including normal excavation and backfill, piping, valves and boxes, curb and boxes, drip pots, regulators and master meter installations		\$5,000.00
ID0000624	Flooring Replacement Non Routine(Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Other)	Replacement of VCT and Carpet Flooring - Non Routine		\$2,000.00
	Subtotal of Estimated Cost			\$1,115,592.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 2		2027		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,115,592.00
ID0000499	Water Line Repipe(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Re-pipe units		\$15,000.00
ID0000509	Landscape Replacement(Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Playground Areas - Equipment,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Site Work (1480)-Water Lines/Mains)	Replace common area landscape and lighting		\$20,000.00
ID0000526	Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other)	Paint ext. of buildings. Abate lead paint as necessary		\$20,000.00
ID0000527	Pre Fab Storage Sheds(Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Other)	Install Pre Fab Skid Type Storage Sheds at Units		\$20,000.00
ID0000528	Windows Replacement(Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Windows)	Install replacement windows.		\$12,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 2		2027		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000529	Operations(Operations (1406))	Operations		\$200,000.00
ID0000530	Management Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software and Training needed for capital fund management		\$5,000.00
ID0000531	Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administration		\$115,000.00
ID0000532	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0000533	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees. 5 Year Environmental Review and Energy Audit consultant fees.		\$36,000.00
ID0000534	VCT Tile Replacement/ Asbestos Abatement AMP Wide(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$26,000.00
ID0000535	Site Work/ Landscaping/ADA (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Site landscaping, ADA, sidewalk replacements		\$15,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year		2027		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000536	Appliance Upgrade- Amp Wide(Dwelling Unit-Interior (1480)-Appliances)	Replace Unit Appliances (60)		\$36,000.00
ID0000537	Bathroom Remodel(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Bathrooms		\$75,000.00
ID0000538	Energy Upgrades - Building Amp Wide(Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts)	Replace building components for energy upgrade		\$48,000.00
ID0000539	HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$50,000.00
ID0000540	Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and Showers)	ADA accessibility improvements to units		\$12,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
	2	2027		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000541	Kitchen Remodel(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Kitchen		\$60,000.00
ID0000543	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0000544	Sewer Lateral Replacement(Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$50,000.00
ID0000545	Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding)	Paint ext. of buildings. Abate lead paint as necessary.		\$10,000.00
ID0000546	Lead Based Paint Abatement Amp Wide(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Siding)	lead based paint - removal, enclosure, encapsulation, and replacement		\$75,000.00
ID0000547	Door Replacement(Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	Replace Unit Interior, Exterior, Storage and Water Heater Vent Doors.		\$20,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 2		2027		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000548	HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$50,000.00
ID0000549	Site Signage(Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Signage)	Replace and Upgrade Existing Property Site Signage		\$30,000.00
ID0000550	Water Intrusion Mitigation and Remediation (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Water intrusion mitigation and remediation covers cleaning, drying, sanitizing and repairing. Mold remediation.		\$23,000.00
ID0000572	Energy Upgrades - Electric Amp Wide(Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing)	Replace unit light fixtures, panels, wiring and appliances for energy upgardes		\$30,000.00
ID0000599	Landscaping Rehab - Tree Work, Amp Wide(Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other)	Prune, remove and replace landscaping trees that are diseased or impacting site infrastructure.		\$10,000.00
ID0000602	Interior Painting(Dwelling Unit-Interior (1480)-Interior Painting (non routine))	Paint Interior of buildings. Abate lead paint as necessary		\$30,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3		2028		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,115,592.00
ID0000521	HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical)	Replace HVAC systems		\$60,000.00
ID0000551	Appliance Upgrade Amp Wide(Dwelling Unit-Interior (1480)-Appliances)	Replace Unit Appliances (70)		\$10,000.00
ID0000552	Kitchen Remodel(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing)	Remodel kitchen and replace unit cabinets and counter top systems		\$60,000.00
ID0000553	Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding)	Paint ext. of buildings. Abate lead paint as necessary.		\$60,000.00
ID0000555	Replace Porch/Sidewalk/ADA Improvements(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Site Work (1480)-Pedestrian paving)	Replace porch/Sidewalk and ADA improvements to unit entries		\$16,000.00
ID0000557	Install Solar Panels(Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Landscape,Non-Dwelling Exterior (1480)-Canopies,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Roofs,Non-	Install solar panels for common area electrical system.		\$20,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year				
3	2028			
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Dwelling Exterior (1480)-Siding,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Site Utilities)			
ID0000558	Roof, Fascia, Gutter, Downspout Rehab, Roof Anchors(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits)	Replace Roof Fascia, Gutter, Downspouts and Roof Anchors		\$25,000.00
ID0000559	Unit Interior ADA Upgrades(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and Showers)	ADA accessibility improvements to units		\$30,000.00
ID0000560	Landscaping Rehab - Tree Work, Amp Wide(Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other)	Prune, remove and replace landscaping trees that are diseased or impacting site infrastructure.		\$70,000.00
ID0000561	Sewer Investigation and Replacement(Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Investigate damaged, blocked, crushed sewer laterals and mainlines and replace as required.		\$75,000.00
ID0000562	Resurface Roads(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping)	Resurface roads, repave, seal coat, striping, curb gutter and sidewalk replacement.		\$40,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3 2028				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000564	VCT Tile Replacement/ Asbestos Abatement (Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$50,000.00
ID0000565	Site Work/ Landscaping/ADA (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Site landscaping, ADA, sidewalk replacements		\$35,000.00
ID0000566	Operations(Operations (1406))	Operations		\$50,000.00
ID0000567	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0000568	Management Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software and Training needed for capital fund management		\$5,000.00
ID0000569	Administration(Administration (1410)-Other,Administration (1410)-Salaries,Administration (1410)-Sundry)	Administration		\$115,000.00
ID0000570	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3 2028				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000571	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County Fees.		\$50,000.00
ID0000574	Energy Upgrades - Building Amp Wide(Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding)	Replace building components for energy upgrade		\$50,000.00
ID0000575	Smoke Detectors and CO Detectors (Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other)	Replace Smoke Detectors and CO Detectors		\$5,000.00
ID0000576	Fencing (Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Landscape)	Replace site fencing and in front and back yards as needed.		\$50,000.00
ID0000578	Site Security (Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Carports - Surface Garage,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling	Perimeter fencing, access control gates, LED Lighting upgrade, deadbolt locks, electronic locks, security window screens, security door screens		\$45,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3 2028				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Playground Areas - Equipment,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Interior (1480)-Security,Non-Dwelling Site Work (1480)-Signage,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc)			
ID0000579	Landscape Replacement(Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting)	Replace common area landscape and lighting		\$20,000.00
ID0000600	Stucco and Siding (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits)	Stucco and other Siding replacements including Painting		\$27,592.00
ID0000603	Interior Painting(Dwelling Unit-Interior (1480)-Interior Painting (non routine))	Paint Interior of buildings. Abate lead paint as necessary		\$30,000.00
ID0000615	Exterior Lighting Upgrades(Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Site Work (1480)-Lighting,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Site Work (1480)-Lighting)	Install Upgraded Exterior Lighting		\$50,000.00
ID0000618	Asbestos, Lead and Hazardous Materials (Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes,Dwelling Unit-Exterior (1480)-Tuck-Pointing,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non	Testing, Abatement and Clearance Testing of Hazardous Materials		\$50,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 3 2028				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	cyclical), Dwelling Unit-Interior (1480)-Call-for-Aid Systems, Dwelling Unit-Interior (1480)-Commodities, Dwelling Unit-Interior (1480)-Electrical, Dwelling Unit-Interior (1480)-Flooring (non routine), Dwelling Unit-Interior (1480)-Interior Doors, Dwelling Unit-Interior (1480)-Interior Painting (non routine), Dwelling Unit-Interior (1480)-Kitchen Cabinets, Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets, Dwelling Unit-Interior (1480)-Mechanical, Dwelling Unit-Interior (1480)-Other, Dwelling Unit-Interior (1480)-Plumbing, Dwelling Unit-Interior (1480)-Tubs and Showers, Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving, Dwelling Unit-Site Work (1480)-Curb and Gutter, Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures, Dwelling Unit-Site Work (1480)-Electric Distribution, Dwelling Unit-Site Work (1480)-Fence Painting, Dwelling Unit-Site Work (1480)-Landscape, Dwelling Unit-Site Work (1480)-Lighting, Dwelling Unit-Site Work (1480)-Other, Dwelling Unit-Site Work (1480)-Parking, Dwelling Unit-Site Work (1480)-Pedestrian paving, Dwelling Unit-Site Work (1480)-Playground Areas - Equipment, Dwelling Unit-Site Work (1480)-Seal Coat, Dwelling Unit-Site Work (1480)-Sewer Lines - Mains, Dwelling Unit-Site Work (1480)-Signage, Dwelling Unit-Site Work (1480)-Storm Drainage, Dwelling Unit-Site Work (1480)-Striping, Dwelling Unit-Site Work (1480)-Water Lines/Mains, Dwelling Unit - Demolition (1480)			
ID0000623	Physical Needs Assessment(Contract Administration (1480)-Other Fees and Costs, Contract Administration (1480)-Other)	comprehensive evaluation of a property's existing physical condition, identifying deficiencies, code compliance issues, and anticipated repair or replacement needs		\$5,000.00
	Subtotal of Estimated Cost			\$1,115,592.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 4 2029				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,115,592.00
ID0000511	Landscape Replacement(Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains)	Replace common area landscape and lighting		\$35,000.00
ID0000517	Relocation Costs(Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0000518	Management Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software Materials and Training needed for capital fund managment		\$5,000.00
ID0000520	Appliance Upgrade (Dwelling Unit-Interior (1480)-Appliances)	Replace Selected Unit Appliances		\$20,000.00
ID0000580	Operations(Operations (1406))	Operations		\$40,000.00
ID0000581	Administration(Administration (1410)-Salaries)	Administration		\$115,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 4		2029		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000582	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00
ID0000583	Fees and Costs(Contract Administration (1480)-Other Fees and Costs)	Fees and Costs associated with Architectural, Engineering, Permits, City and County fees.		\$100,000.00
ID0000584	VCT Tile Replacement(Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic		\$30,000.00
ID0000585	Roof Replacement(Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Roofs)	Replace Roof, Fascia, Vents, Gutter and Downspouts		\$250,000.00
ID0000586	Unit Interior ADA Accessibility Improvements (Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Tubs and Showers)	ADA Accessibility Improvements to Units		\$175,000.00
ID0000587	Water Heater Replacement(Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Plumbing)	Replace Water Heaters		\$55,991.00
ID0000588	Site Work/Landscaping(Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Striping)	Site Landscaping, ADA Site Work, Sidewalk Replacement, Signage, Striping		\$50,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5		2030		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	BUTTE COUNTY (CA043000001)			\$1,115,592.00
ID0000504	Exterior Painting(Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Siding)	Paint ext. of buildings. Abate lead paint as necessary.		\$10,000.00
ID0000507	Unit Interior ADA Upgrades(Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Tubs and Showers)	ADA accessibility improvements to units		\$65,000.00
ID0000508	Stucco, Siding/Painting.(Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Other)	stucco, Siding including painting.		\$38,592.00
ID0000512	Landscape Replacement(Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving)	Replace common area landscape and lighting		\$50,000.00
ID0000516	Audit(Contract Administration (1480)-Audit)	Audit		\$2,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5 2030				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000542	Windows Replacement (Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Exterior (1480)-Siding)	Install replacement windows.		\$50,000.00
ID0000556	Install Retaining Wall(Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Storm Drainage)	Install retaining wall along the back of the east side units to stop hillside erosion.		\$10,000.00
ID0000573	Bathroom Remodel(Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers)	Remodel Bathrooms, replace tub and shower combos, toilets, sinks, faucets, shower heads		\$60,000.00
ID0000577	Community Bldg. Interior and Exterior Remodel(Non-Dwelling Exterior (1480)-Balconies and Railings,Non-Dwelling Exterior (1480)-Canopies,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Exterior (1480)-Doors,Non-Dwelling Exterior (1480)-Foundation,Non-Dwelling Exterior (1480)-Gutters - Downspouts,Non-Dwelling Exterior (1480)-Landings and Railings,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Mail Facilities,Non-Dwelling Exterior (1480)-Other,Non-Dwelling Exterior (1480)-Paint and Caulking,Non-Dwelling Exterior (1480)-Roofs,Non-Dwelling Exterior (1480)-Siding,Non-Dwelling Exterior (1480)-Soffits,Non-Dwelling Exterior (1480)-Stairwells and Fire Escapes,Non-Dwelling Exterior (1480)-Tuck Pointing,Non-Dwelling Exterior (1480)-Windows,Non-Dwelling Interior (1480)-Appliances,Non-Dwelling Interior (1480)-Common Area Bathrooms,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Flooring,Non-Dwelling Interior (1480)-Common Area Kitchens,Non-Dwelling Interior (1480)-Common Area Painting,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Plumbing,Non-Dwelling Interior (1480)-Security,Non-Dwelling Interior (1480)-Shop Non-Dwelling Interior (1480)-Storage Area)	Perform Interior and Exterior Remodel at Community Bldg.		\$250,000.00
ID0000592	Administration(Administration (1410)-Other,Administration (1410)-Salaries)	Administration		\$10,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5		2030		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000593	Operations(Operations (1406))	OPerations		\$10,000.00
ID0000594	Managment Improvements(Management Improvement (1408)-Other,Management Improvement (1408)-Staff Training,Management Improvement (1408)-System Improvements)	Software and Training needed for capital fund management		\$5,000.00
ID0000595	Relocation Costs(Contract Administration (1480)-Other,Contract Administration (1480)-Other Fees and Costs,Contract Administration (1480)-Relocation)	Relocate Residents Due to Construction Activities		\$10,000.00
ID0000596	VCT Tile Replacement/ Asbestos Abatement (Dwelling Unit-Interior (1480)-Flooring (non routine))	Replace VCT Tile and remove and abate asbestos containing existing tile and mastic.		\$50,000.00
ID0000597	Site Work/Landscaping/ADA (Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Playground Areas - Equipment,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Non-Dwelling Site Work (1480)-Asphalt - Concrete - Paving,Non-Dwelling Site Work (1480)-Curb and Gutter,Non-Dwelling Site Work (1480)-Dumpster and Enclosures,Non-Dwelling Site Work (1480)-Fence Painting,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Playground Areas - Equipment,Non-Dwelling Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Site Utilities,Non-Dwelling Site Work (1480)-Storm	Site landscaping, ADA, sidewalk replacements		\$10,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5		2030		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000601	HVAC System(Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Non-Dwelling Construction - Mechanical (1480)-Cooling Equipment - Systems,Non-Dwelling Construction - Mechanical (1480)-Electric Distribution,Non-Dwelling Construction - Mechanical (1480)-Heating Equipment - System,Non-Dwelling Construction - Mechanical (1480)-Hot Water Heaters,Non-Dwelling Construction - Mechanical (1480)-Security - Fire Alarm,Non-Dwelling Construction - Mechanical (1480)-Interior Painting(Dwelling Unit-Interior (1480)-Interior Painting (non routine))	Replace HVAC systems		\$60,000.00
ID0000604	Interior Painting(Dwelling Unit-Interior (1480)-Interior Painting (non routine))	Paint Interior of buildings. Abate lead paint as necessary		\$65,000.00
ID0000606	Fencing (Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Playground Areas - Equipment)	Replace site fencing and in front and back yards as needed.		\$60,000.00
ID0000607	Screen Door Replacement(Dwelling Unit-Exterior (1480)-Exterior Doors)	Install screen doors at units, security screen doors		\$10,000.00
ID0000608	Water Intrusion Mitigation and Remediation (Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc.Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns	Water intrusion mitigation and remediation covers cleaning, drying, sanitizing and repairing. Mold remediation.		\$60,000.00
ID0000613	Site Signage(Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Landscape,Non-Dwelling Site Work (1480)-Signage)	Replace and Upgrade Existing Property Site Signage		\$50,000.00

Capital Fund Program - Five-Year Action Plan

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5		2030		
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
ID0000616	Exterior Lighting Upgrades(Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Site Work (1480)-Lighting,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Other,Non-Dwelling Site Work (1480)-Lighting)	Install Upgraded Exterior Lighting		\$70,000.00
ID0000617	Asbestos, Lead and Hazardous Materials (Dwelling Unit-Exterior (1480)-Balconies-Porches-Railings-etc,Dwelling Unit-Exterior (1480)-Building Slab,Dwelling Unit-Exterior (1480)-Canopies,Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Columns and Porches,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Paint and Caulking,Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Foundations,Dwelling Unit-Exterior (1480)-Gutters - Downspouts,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Mail Facilities,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Exterior (1480)-Roofs,Dwelling Unit-Exterior (1480)-Siding,Dwelling Unit-Exterior (1480)-Soffits,Dwelling Unit-Exterior (1480)-Stairwells - Fire Escapes,Dwelling Unit-Exterior (1480)-Tuck-Pointing,Dwelling Unit-Exterior (1480)-Windows,Dwelling Unit-Interior (1480)-Appliances,Dwelling Unit-Interior (1480)-Bathroom Counters and Sinks,Dwelling Unit-Interior (1480)-Bathroom Flooring (non cyclical),Dwelling Unit-Interior (1480)-Call-for-Aid Systems,Dwelling Unit-Interior (1480)-Commodes,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Flooring (non routine),Dwelling Unit-Interior (1480)-Interior Doors,Dwelling Unit-Interior (1480)-Interior Painting (non routine),Dwelling Unit-Interior (1480)-Kitchen Cabinets,Dwelling Unit-Interior (1480)-Kitchen Sinks and Faucets,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Interior (1480)-Plumbing,Dwelling Unit-Interior (1480)-Tubs and Showers,Dwelling Unit-Site Work (1480)-Asphalt - Concrete - Paving,Dwelling Unit-Site Work (1480)-Curb and Gutter,Dwelling Unit-Site Work (1480)-Dumpsters and Enclosures,Dwelling Unit-Site Work (1480)-Electric Distribution,Dwelling Unit-Site Work (1480)-Fence Painting,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Landscape,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work (1480)-Pedestrian paving,Dwelling Unit-Site Work (1480)-Playground Areas - Equipment,Dwelling Unit-Site Work (1480)-Seal Coat,Dwelling Unit-Site Work (1480)-Sewer Lines - Mains,Dwelling Unit-Site Work (1480)-Signage,Dwelling Unit-Site Work (1480)-Storm Drainage,Dwelling Unit-Site Work (1480)-Striping,Dwelling Unit-Site Work (1480)-Water Lines/Mains,Dwelling Unit - Demolition (1480))	Testing, Abatement and Clearance Testing of Hazardous Materials		\$60,000.00
ID0000619	Site Security (Dwelling Unit-Exterior (1480)-Carports -Surface Garage,Dwelling Unit-Exterior (1480)-Decks and Patios,Dwelling Unit-Exterior (1480)-Exterior Doors,Dwelling Unit-Exterior (1480)-Exterior Lighting,Dwelling Unit-Exterior (1480)-Exterior Stairwells - Fire Escape,Dwelling Unit-Exterior (1480)-Landings and Railings,Dwelling Unit-Exterior (1480)-Other,Dwelling Unit-Interior (1480)-Electrical,Dwelling Unit-Interior (1480)-Mechanical,Dwelling Unit-Interior (1480)-Other,Dwelling Unit-Site Work (1480)-Fencing,Dwelling Unit-Site Work (1480)-Lighting,Dwelling Unit-Site Work (1480)-Other,Dwelling Unit-Site Work (1480)-Parking,Dwelling Unit-Site Work	Perimeter fencing, access control gates, LED Lighting upgrade, deadbolt locks, electronic locks, security window screens, security door screens		\$50,000.00

Part II: Supporting Pages - Physical Needs Work Statements (s)				
Work Statement for Year 5 2030				
Identifier	Development Number/Name	General Description of Major Work Categories	Quantity	Estimated Cost
	Signage,Non-Dwelling Exterior (1480)-Doors,Non-Dwelling Exterior (1480)-Landings and Railings,Non-Dwelling Exterior (1480)-Lighting,Non-Dwelling Exterior (1480)-Mail Facilities,Non-Dwelling Exterior (1480)-Other,Non-Dwelling Exterior (1480)-Windows,Non-Dwelling Interior (1480)-Administrative Building,Non-Dwelling Interior (1480)-Common Area Bathrooms,Non-Dwelling Interior (1480)-Common Area Finishes,Non-Dwelling Interior (1480)-Common Area Kitchens,Non-Dwelling Interior (1480)-Common Area Washers,Non-Dwelling Interior (1480)-Community Building,Non-Dwelling Interior (1480)-Day Care Center,Non-Dwelling Interior (1480)-Doors,Non-Dwelling Interior (1480)-Electrical,Non-Dwelling Interior (1480)-Laundry Areas,Non-Dwelling Interior (1480)-Mechanical,Non-Dwelling Interior (1480)-Other,Non-Dwelling Interior (1480)-Security,Non-Dwelling Interior (1480)-Shop,Non-Dwelling Interior (1480)-Storage Area,Non-Dwelling Site Work (1480)-Fencing,Non-Dwelling Site Work (1480)-Lighting,Non-Dwelling Site Work (1480)-Signage,Non-Dwelling Site Work (1480)-Site Utilities)			
	Subtotal of Estimated Cost			\$1,115,592.00